

MAY CREEK LANDFILL  
Renton, Washington



Photo 1 Site debris pile consisting of heterogeneous waste including building materials and vehicle parts.

Direction: West Date: 2/25/16 Time: 13:37



Photo 3 One of several pathways throughout the site debris piles. A mobile home is positioned at the end of this pathway.

Direction: East Date: 2/25/16 Time: 13:38

TDD Number: 16-02-0007  
Photographed by: Brad Martin



Photo 2 Large household appliances are grouped among other unsorted debris including tires and plastic.

Direction: Northeast Date: 2/25/16 Time: 13:37



Photo 4 Several boats are positioned on top of a pile of varying debris beyond the crude roadway.

Direction: South Date: 2/25/16 Time: 13:45



MAY CREEK LANDFILL  
Renton, Washington




Photo 5 A pond is on site with debris around the perimeter.

Direction: West

Date: 2/25/16

Time: 13:45



Photo 7 Large oil tanker on trailer containing minimal amounts of oil sludge on the base.

Direction: West

Date: 2/25/16

Time: 13:50

TDD Number: 16-02-0007  
Photographed by: Brad Martin



Photo 6 Product spilled and mixed in with debris.

Direction: Down

Date: 2/25/16

Time: 13:49



Photo 8 Vacated transportation vehicles scrapped on site used as a storage depot for chemical storage.

Direction: East

Date: 2/25/16

Time: 15:29

**Pillon - 000241**



MAY CREEK LANDFILL  
Renton, Washington



Photo 9 Excess chemical containers sitting stacked and exposed outside next to a transportation vehicle used as chemical storage.

Direction: East Date: 2/25/16 Time: 15:29



Photo 11 Several individuals living on site in mobile homes on top of debris piles.

Direction: Southeast Date: 2/25/16 Time: 15:48

TDD Number: 16-02-0007  
Photographed by: Brad Martin



Photo 10 Transportation vehicles and drums grouped together on the South Eastern quadrant of the landfill.

Direction: Southeast Date: 2/25/16 Time: 15:48



Photo 12 A fire truck, tow truck, and RV are among several other vehicles placed near a structure on the property.

Direction: Southeast Date: 2/25/16 Time: 16:00

MAY CREEK LANDFILL  
Renton, Washington

TDD Number: I6-02-0007  
Photographed by: Brad Martin



Photo 13 Oil sheening was visible in several puddles on site pathways through the debris piles.

---

*Direction:* Northwest      *Date:* 2/25/16      *Time:* 16:00

---













Pillon - 000972

















































Pillon - 001378









Pillon - 001770





Pillon - 001783





Pillon - 001790









Pillon - 001840





Pillon - 002894





Pillon - 002895





02/25/2016 10:50





Pillon - 002915













02/25/2016 11:12

Pillon - 002927













02/25/2016 11:26





02/25/2016 11:45

Pillon - 002964



